Under Review Notification

Raised By: Vanessa Morel Product #: RBE332A94-2791-00

Date: 2019.10.28 Product Name: SET OF BLOCKS TAIL ROTOR

		"Y" or "N" Required for Each Part									
		Do not leave blank									
Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers		Quarantine Tooling (Jigs, Fixtures, etc.)	Re-Work Stock	IPP Under Review (Enginer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")	Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
RBE332A94-2791-00	RBE332A94-2791-00 Rev	Υ	Υ	N	Υ	Υ	Ν	N	N	19-1047	See below
	· · · · · · · · · · · · · · · · · · ·										

Description of Issue:

Issues stated on ADR (Procurement issues)

RBE332A94-2791-00 and items -1, -3, -5, -7, -9, -11 and -13 must be put on **HOLD** in Plex

RBE332A94-2791-00 Finish good stock can be use as is

Items -1, -3, -5, -7, -9, -11 and -13 stock must be put in quarantine

No new manufacturing is permitted until Engineering release new Rev

Can remain on website with a note to contact sales for a quote. They must NOT be able to put the tool into cart

'P" Part must be put on HOLD in Plex as well

Distribution: VP Operations Director of Engineering Customer Support Manager Technical Support

Director of OperationsChief EngineerProduction EngineersProduct Manager - Solutions ProviderDirector Quality AssuranceEngineering Project ManagersProduction PlannersSupply Chain Director / Senior Buyer

QC Coordinator Engineering Clerk Purchasing Manager Marketing Eugene